



Important Notice – **04/12/25**

Alliance Environmental Services Ltd (AES) in conjunction with Cheshire East Bereavement Services (CEBS) on behalf of Staffordshire Moorlands District Council.

AES Ltd have completed a safety survey of the memorials in **St Giles', Cheadle**

We are responsible to ensure the safety of all visitors to the cemeteries under our control and following fatalities and injuries in other parts of the country caused by falling memorials, we are following advice by the Health and Safety Executive the Ministry of Justice and the Diocesan Advisory Committee. This churchyard is subject to the Faculty Jurisdiction of the Church of England, exercised through the Consistory Court.

During our latest survey we identified the following memorial's have failed the testing and in need of remedial work.

- MOSS, WILLIAM 1919
- WHITEHURST, RICHARD 1894
- ARNOLD, FREDERICK CHARLES 1892
- COLLIS, JOHN POWER 1881
- KEATES, WILLIAM 1874

The primary responsibility for maintenance of the memorial rests with the owner of the memorial. We require to know if the owners intend to carry out the essential remedial work's required.

If we do not hear from the owners by **02/01/26** then it will be assumed that you do not wish to carry out the work and CEBS will then arrange for the necessary works to make the memorial safe. This work will be conducted at a cost however we will seek to recoup that cost from the owner.



Cemetery Office, 87 Prestbury Road, Macclesfield, Cheshire, SK10 3BU
alliancecemeteries@cheshireeast.gov.uk Telephone - 01625 383945